

REPLACEMENT FOR

XJR/X300

REPLACEMENT FOR

X308

REPLACEMENT FOR

X-TYPE '01-

883-1404
SIDE LAMP
 LNA4812AB
 PCS CFT



W5W TBA

883-1602
FRONT LAMP
 R LNC4800AD
 L LNC4801AD
 PCS CFT



P21W TBA

883-1401-AE X TYPE
SIDE LAMP
 R 02C2S3046
 L 02C2S3045
 PCS CFT



W5W TBA

883-1403
FRONT REFLECTOR
 DBC10889
 PCS CFT



TBA

883-1402
SIDE LAMP
 R LNC5020AB
 L LNC5021AB
 PCS CFT



TBA

883-1401P3BE-C X TYPE
SIDE LAMP
 50PRS 0.86CFT



WY5W

883-1601
FRONT LAMP
 R LNA4800AB
 L LNA4801AB
 PCS CFT



P21W TBA

883-1401P3BE-S X TYPE
SIDE LAMP
 50PRS 0.86CFT




WY5W

883-1903
TAIL LAMP
 R
 L
 PCS CFT



PY21W/P21W/5W/P21W/P21W/R5W TBA

883-1405 X TYPE
SIDE LAMP
 R 1X43-13B454-AC
 L 1X43-13B455-AC
 R 1X43-15A424-AC
 L 1X43-15A425-AC
 PCS CFT



W5W TBA

883-1902
TAIL LAMP
 R 2VP236009-02
 L 2VP236009-01
 PCS CFT



PY21W/P21W/5W/P21W/P21W/R5W TBA

883-1901 S TYPE
TAIL LAMP
 R 2VP238021-02
 L 2VP238021-01
 PCS CFT



P21W/PY21W/P21W/4W/R5W TBA