



REPLACEMENT FOR

2105/2106/2107 '83-'88

REPLACEMENT FOR

2108 SAMARA '86-'90

662-1104-LD 2105 43T
HEAD LAMP
 R 2105-3711010-10
 L 2105-3711011-10
 6PCS 5.60CFT



H4

662-1103-LD 2107 43T
HEAD LAMP
 LD:
 R 2107-3711010-11
 L 2107-3711011-11
 4PCS 5.60CFT

RD:
 R 2107-3711010-10
 L 2107-3711011-10



H4

662-1101-LDEHU 43T
HEAD LAMP
 R
 L
 6PCS 6.28CFT



H4/T4W/P21W

662-1401
SIDE LAMP
 R
 L
 PCS CFT



W5W

TBA

Empty space

662-1101-LD-E 43T
HEAD LAMP
 R 2108-3711010-01
 L 2108-3711011-01
 6PCS 6.28CFT



H4/T4W

662-1902 2105
TAIL LAMP
 R
 L
 10PCS CFT



TBA

662-1901 2107
TAIL LAMP
 R
 L
 PCS CFT



TBA

662-1501-UE
CORNER LAMP
 R
 L
 20PCS 1.89CFT



P21W

662-1903 NIVA 1600CC 2106
TAIL LAMP
 R 2105-3716010-01
 L 2105-3716011-01
 PCS CFT



TBA

Empty space

662-1910 2104
TAIL LAMP
 R
 L
 PCS CFT



TBA

