



REPLACEMENT FOR
**SUMMIT SEDAN '89-'92/
 HATCHBACK '91-'92**

314-1121-AS

HEAD LAMP ASSY
 R MB598450
 L MB598449
 6PCS 4.34CFT
 WT:35.02LBS

PARTSLINK NO:
 R MI2503109
 L MI2502109



USA BUILT
 GLASS LENS

REPLACEMENT FOR
**SUMMIT
 COUPE/SEDAN '93-'96**

314-1123-AS

HEAD LAMP ASSY
 R MB912964
 L MB912963
 6PCS 4.05CFT
 WT:24.67LBS

PARTSLINK NO:
 R MI2503108
 L MI2502108








314-1509-AS

PARK/SIGNAL LAMP ASSY
 R MB821052
 L MB821051
 20PCS 2.80CFT
 WT:15.42LBS

PARTSLINK NO:
 R MI2521109
 L MI2520109



COUPE MODEL



WWW.REFORMAUTO.RU

EG



REPLACEMENT FOR
TALON '90-'91

REPLACEMENT FOR
TALON '92-'94

REPLACEMENT FOR
TALON '95-'98



314-1122-AS
HEAD LAMP ASSY
 R MB861294
 L MB861293
 6PCS 7.45CFT
 WT:35.24LBS

PARTSLINK NO:
 R MI2503103
 L MI2502103



314-1102-AS
HEAD LAMP COMB ASSY
 R MR162466
 L MR162465
 4PCS 6.6CFT
 WT:35.02LBS

PARTSLINK NO:
 R MI2503104
 L MI2502104



314-1502-AS
COMBINATION LAMP ASSY
 R MB597766
 L MB597765
 20PCS 3.15CFT
 WT:19.78LBS

PARTSLINK NO:
 R MI2521112
 L MI2520112



314-1503-AS
PARK/CLEARANCE LAMP ASSY
 R MB861296
 L MB861295
 20PCS 3.52CFT
 WT:14.32LBS

PARTSLINK NO:
 R MI2521104
 L MI2520104



314-1401-AS
SIDE MARKER LAMP ASSY
 R MB882124
 L MB882123
 50PCS 0.93CFT
 WT:5.29LBS

PARTSLINK NO:
 R MI2551105
 L MI2550105








314-1606-AS
SIGNAL LAMP ASSY
 R MB597764
 L MB597763
 20PCS 6.70CFT
 WT:40.09LBS

PARTSLINK NO:
 R MI2531103
 L MI2530103

'79-'93



USA BUILT



EG

WWW.REFORMAUTO.RU



REPLACEMENT FOR
VISION '93-'95

REPLACEMENT FOR
VISION '96-'97

<p>333-1156-US '94-'95 HEAD LAMP UNIT R 4762058 L 4762059 L 4530343 6PCS 2.02CFT WT:10.35LBS</p> <p>PARTSLINK NO: R CH2503102 L CH2502102</p>  <p>W/O BULB</p>	<p>333-1157-US HEAD LAMP UNIT R 4856562 L 4856563 6PCS 2.02CFT WT:10.35LBS</p> <p>PARTSLINK NO: R CH2503111 L CH2502111</p>  <p>W/O BULB</p>	
<p>333-1107-US '93 HEAD LAMP UNIT R 04746436 L 04746437 6PCS 2.02CFT WT:10.13LBS</p> <p>PARTSLINK NO: R CH2519105 L CH2518105</p>  <p>W/O BULB</p>	<p>333-1705-UD BRKT,HEAD LAMP MTG R 4746446 L 4746447 10PCS 5.26CFT WT:16.96LBS</p> <p>PARTSLINK NO: R CH2515105 L CH2514105</p> 	
<p>333-1506-US '93-'95 PARK/SIGNAL/SIDE MARKER LAMP UNIT R 4746440 L 4746441 20PCS 3.56CFT WT:18.5LBS</p> <p>PARTSLINK NO: R CH2521134 L CH2520134</p> 		
<p>333-1705-UD BRKT,HEAD LAMP MTG R 4746446 L 4746447 10PCS 5.26CFT WT:16.96LBS</p> <p>PARTSLINK NO: R CH2515105 L CH2514105</p> 		

EG