



REPLACEMENT FOR

LASER '81-'82

REPLACEMENT FOR

LASER '83-'85

231-1105N-RD

43T

HEAD LAMP
BA15-89-661
BA30-51-030
8PCS 3.0CFT



H4

231-1106-RD
LD

43T

HEAD LAMP
LD:
R BE08-51-030A
L BE08-51-040A
6PCS 3.19CFT



H4

231-1202

GL1.5

LIGHT CASE
R BA16-89-662
L BA16-89-667
10PCS 4.34CFT



231-1205

LIGHT RING
R B060-50-421
L B060-50-431
PCS CFT



TBA

231-1203

L1.3

LIGHT CASE
R BA15-89-662
L BA15-89-667
PCS CFT



TBA

231-1504

CORNER LAMP
R BE80-51-060A
L BE80-51-070A
50PCS 5CFT



00-231-1202

LIGHT CASE LENS
R BA14-51-062
L BA14-51-072
100PCS 2.6CFT



231-1908

GL1.34

TAIL LAMP
R BA37-51-150
L BA37-51-160
PCS CFT



TBA

231-1911

GL1.5 4D

TAIL LAMP
R B061-51-150
L B061-51-160
PCS CFT



TBA

231-1912

GL1.34

TAIL LAMP
R B071-51-150
L B071-51-160
PCS CFT



TBA

231-1910

5D

TAIL LAMP
R BA14-51-150
L BA14-51-160
10PCS 2.24CFT



231-1909

GL1.3

TAIL LAMP
R BA38-51-150
L BA38-51-160
8PCS 5.90CFT



231-1913

H/BACK

TAIL LAMP
R BD76-51-150
L BD76-51-160
10PCS 3.50CFT





REPLACEMENT FOR

**LASER '86(4 DOOR)
GC METEOR MK I**

REPLACEMENT FOR

LASER '86(5 DOOR) TX3/KC

REPLACEMENT FOR

**LASER '88-'93(4 DOOR)
METEOR MK II**

231-1107-RD
HEAD LAMP LD
RD:
R 8BB8-51-030
L 8BB8-51-040
LD:
R BH46-51-030
L BH46-51-040
6PCS 3.32CFT



H4/W5W

231-1108-RD 43T
HEAD LAMP
RD:
R 8BB6-51-030
L 8BB6-51-040
LD:
R BH43-51-030
L BH43-51-040
6PCS 4.49CFT



H4

231-1109-LD 43T
HEAD LAMP
RD:
R 8BBY-51-030
L 8BBY-51-040
LD:
R 8N24-51-030
L 8N24-51-040
6PCS 4.9CFT



H4

231-1505
CORNER LAMP
R B173-51-090
L B173-51-100
50PCS 3.2CFT



231-1506-A
CORNER LAMP
R B156-51-060
L B156-51-070
50PCS 4.8CFT



231-1508-U
CORNER LAMP
R B406-51-060
L B406-51-070
25PCS
5.35CFT



231-1915
TAIL LAMP
GREY RIM
R B173-51-150
L B173-51-160
PCS CFT



TBA

231-1916
TAIL LAMP
R B156-51-150
L B156-51-160
10PCS 3.40CFT



231-1918-A/U
TAIL LAMP
R B406-51-150
L B406-51-160
12PCS 4.20CFT



231-1914 L 1.3 BLACK RIM
TAIL LAMP
R B174-51-150
L B174-51-160
PCS CFT



TBA



REPLACEMENT FOR

LASER '88-'93(WAGON)

REPLACEMENT FOR

LASER '88(5 DOOR) KE H/BACK

REPLACEMENT FOR

LASER '90

216-1107-RD-E
HEAD LAMP LD
 RD:
 R 8FB5-51-030A
 L 8FB5-51-040A
 LD:
 R BA5E-51-030AR
 L BA5E-51-040AA

LD:
 R 8DB5-51-030
 L 8DB5-51-040
 6PCS 4.81CFT
 47-216-1107 GLASS
 10PCS 1.92CFT



H4/W5W

231-1115-RD-E 43T 5D
HEAD LAMP
 R 8BG2-51-030
 L 8BG2-51-040
 6PCS 3.53CFT




H4/W5W

231-1111-RD-E KF '90 43T
HEAD LAMP LD
 RD:
 R 8DBN-51-030
 L 8DBN-51-040
 LD:
 R 8A0S-51-030
 L 8A0S-51-040
 6PCS 3.63CFT



H4

231-1512-A
CORNER LAMP
 R
 L
 20PCS 4.0CFT



12V5W/12V10W

231-1513-AE SOUTH AFRICA TYPE 5D
CORNER LAMP
 R
 L
 20PCS 2.01CFT



P21W

231-1509-YU KF/KH
CORNER LAMP
 R B499-51-060
 L B499-51-070
 10PCS 4.3CFT



231-1929
TAIL LAMP
 R
 L
 PCS CFT



T8A

231-1507 TX3 3D
CORNER LAMP
 R B382-51-060
 L B382-51-070
 20PCS 2.6CFT



231-1919-U KF/KH SEDAN
TAIL LAMP
 R B491-51-150
 L B491-51-160
 10PCS 5CFT



231-1917 3D/5D
TAIL LAMP
 GREY RIM
 R B382-51-150
 L B382-51-160
 10PCS
 3.5CFT



231-1920-A KF/KH H/BACK
TAIL LAMP
 R B499-51-150
 L B499-51-160
 10PCS 5.5CFT





REPLACEMENT FOR

LASER '92 4D



REPLACEMENT FOR

LASER '94 3D AZTEC



REPLACEMENT FOR

LASER '94 4D LIATA

231-1116-RD-E KH '92 43T
LD
 HEAD LAMP
 RD: R B7J61-52-030 L B7J61-52-040
 R 8FBG-51-030 L 8FBG-51-040
 6PCS 4.72CFT

H4

231-1119-LD 43T
 HEAD LAMP
 R BO5P-51-030 L BO5P-51-040
 6PCS 5.81CFT

H4/P21W/W5W

231-1118-RD-EY KJ1 43T
 HEAD LAMP
 R 823E-51-030 L 823E-51-040
 4PCS 5.55CFT

H4/P21W/W5W

231-1509-C '92
 CORNER LAMP
 R L
 10PCS 4.3CFT

231-2003P-AE
 FOG LAMP
 R BO1W-51-68Y L BO1W-51-69Y
 6PRS 3.07CFT

H3

231-1118-RD-E KJ2
LD
 HEAD LAMP
 LD: R BC6H-51-030 L BC6H-51-040
 4PCS 5.55CFT

H4/PY21W/W5W

231-2002-U
 FOG LAMP
 R BO5J-51-68Y L BO5J-51-69Y
 12PCS 5.17CFT

H3

231-1928-U '92
 TAIL LAMP
 R L
 10PCS 3.45CFT

231-1930-2U TAIL LAMP
 R BO5P-51-15Z L BO5P-51-16Z
 10PCS 3CFT

P21W/P21/W5W

231-1402N-AE/UE
 SIDE LAMP
 BO1W-51-120
 A:100PCS 1.22CFT
 U:100PCS 0.56CFT

W5W

231-1931-U KJ1 '95
 TAIL LAMP
 R BO5J-51-150A L BO5J-51-160A
 10PCS 3.34CFT

12V21/5W/12V21W

231-1931-U-1 KJ2 '97
 TAIL LAMP
 R L
 10PCS 3.30CFT

12V21/5W/12V21W



REPLACEMENT FOR

LASER '98 4D



REPLACEMENT FOR

LASER KN/KQ '99-'01



REPLACEMENT FOR

**MAV '01
TAIWAN TYPE**

231-1122-LD '98
HEAD LAMP
R
L
4PCS 4.83CFT

H4/P21W/W5W

231-1133-RD-E
HEAD LAMP
R B27K-51-0K0C
L B27K-51-040C
PCS CFT

H4/W5W TBA

231-1128
HEAD LAMP
R
L
PCS CFT

H1/H7/W5W TBA

231-2004-UE
FOG LAMP
12PCS 3.25CFT

H3

231-1524-UE
CORNER LAMP
R B27K-51-060C
L B27K-51-070C
R B27K-51-06XC
L
PCS CFT


PY21W TBA

231-1944
TAIL LAMP
R
L
PCS CFT

TBA



231-1402P1-VC
SIDE LAMP
50PRS 0.89CFT

WY5W



216-1942-U '98
TAIL LAMP
R
L
10PCS 3.32CFT

12V21W/12V21/5W



231-2901
REFLECTOR
10PCS 2.67CFT



FD